



LG-4681ER1003A

MOTOR ASSEMBLY - WM
LG AFL - WD-12150, WD-12235, WD1290, WD1295



LG-4681FR1194D

MOTOR ASSEMBLY
AFL - WD-10130F, WD-1021WF



LG-5859DD9001A

CIRCULATING PUMP MOTOR
LG dishwasher - LD-2050SH



LG-EAU31357603

MOTOR AC
twin tub: P1160RWP, P1360RWP, P1400ROP



PN-AB35030

MAIN MOTOR
SPEEDQUEEN AWM27



PN-AB835P3

MAIN MOTOR
SPEEDQUEEN top loader - LWS11A, LWS21A
ORIGINAL PART



PN-AD501212

MAIN MOTOR
SPEEDQUEEN tumble dryer - AEM477, EE2107, REM477
ORIGINAL PART



S-DC31-10022N

SPIN MOTOR
SAMSUNG twin tub - SWT90B1P
ORIGINAL PART



TF850-024

SPIN MOTOR
TELEFUNKEN twin tub - TTT850



TSS13

SPIN MOTOR
SAMSUNG - WT1052
OEM REF: DC31-10022T



TSS15

MOTOR, SYNCHRONOUS DRAIN
SAMSUNG top loader: WA80U3, WT80S2P
OEM REF: DC31-20014A